

**EAST Search History****EAST Search History (Interference)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3797	(crash\$4 collision proximity) and (vehic\$4 car mobile automo\$4) and (side satellite) near4 (sensor accelerat\$4 impact\$4) and (axis axes)	USPAT; UPAD	OR	ON	2009/09/23 21:25
L2	269743	("701"/\$ "280"/\$ "340"/\$ "702"/\$ "342"/\$).ccls.	USPAT; UPAD	OR	ON	2009/09/23 21:26
L4	10163	"1" and "2" and (angl\$4 angular\$4) near3 (postive\$4 negative\$4)	USPAT; UPAD	OR	ON	2009/09/23 21:26
L5	3530	4 and (angle degree) near6 ("30" "45" "60" "40" "50")	USPAT; UPAD	OR	ON	2009/09/23 21:27
L6	135	5 and front near6 (sens\$4 acceler\$9)	USPAT; UPAD	OR	ON	2009/09/23 21:27
L7	0	6 and b near3 post\$4	USPAT; UPAD	OR	ON	2009/09/23 21:28

**9/ 23/ 2009 9:28:29 PM****C:\ Documents and Settings\ nguyen2\ My Documents\ EAST\ Workspaces\ 10-565122 Crash which has side sensor in 30-60 degree angle.wsp**